



SAS Superstructure

Location: 04-SF-80-13.2 / 13.9

Client Name: CalTrans

Run date 19-Nov-14

Time 4:19 PM

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 004 Const Calendar Day: 156 Date: 11-Feb-2010 Thursday

Inspector Name: Altamirano, Victor Title: Transportation Engineer

Inspection Type: Continuous

Shift Hours: 08:00 am 10:00 am Break: Over Time:

Federal ID:

Location:

Reviewer: Liu, Tai-Lin

Approved Date:

17-Feb-10 Status: Approved

04-0120F4
04-SF-80-13.2/13.9
Self-Anchored
Suspension Bridge

Weather

Temperature 7 AM 12 PM 4PM

Precipitation Condition

Working Day ☒ If no, explain:

Diary:

Dispute

General Comments

Robert (METS) and I began our inspection of Lift 4E from PP 24 to the west face of PP 26. We inspected first the north Side Plate and worked our way to the south Side Plate each time inspecting the stiffeners on the bottom plate. The iron workers were installing the grating along the center of E line and I was unable to inspect below the grating (see attachment). I did not find or see any visible shipping damage for the portion of the Lift 4E I inspected.

☐

Office: Reviewed multiple submittals and worked on today's diary.

General Comments

Hours worked: 8 hours total.

☐